


BS EN P45S Chip size guide chart



Note: Visually fines may appear more than they are so weighing of fractions is essential
In all fractions on sieving there will be an element of pencilling however the extreme as above stands as extreme.